

**Questions and Answers**  
**Solicitation No. 19RP3820Q0102**  
**Rehabilitation of West and South Guard Tower CH for the U.S. Embassy Manila**

Q: Is it allowed to weld on the steel pipe for temporary scaffolding support?

A: **Yes/Acceptable.**

Q: In solicitation documents paragraph 1.5.1.3 it is stated "the contractor shall utilize the services of experience personnel in the repair of Genset Radiator". As shown on the drawing in dotted line, What kind of materials fixing on the additional concrete to vertical support.

A: **Please refer to Attachment #5 (Drawing), Section B/S-1 of Sheet S-1 and Attachment #6 Division 1, Section 01010, paragraph 1.2, number 1. Demolition/Cutting of underground obstruction). Please refer to revised drawing S-1 under amendment 0003.**

Q: Can I request soft copy drawing the distributed drawings on site is too small.

A: **Please refer to amendment 0001**

Q: Place of removed salvage materials? Where to dispose?

A: **Please refer to Attachment #6, Division 1, Section 01010 paragraph 2.7.1(Clean-up). All demolished items/materials were considered waste materials.**

Q: Due to Covid 19 GCQ situation some offices are not fully in operation and requesting pricing for materials it takes more time is it possible to extend the submission.

A: **Please refer to amendment 0002.**